WORK ORDER REQUEST

December 14, 1956

ro:	LAC				
FROM:	1914				
ITEM #		STOCK NO.	NOMENCLATURE	QUANTITY	•
1		595.3-SP-LT-3056	Adapter-wrench	1	
2		7900-1,28150	Handle-Torque wrench	2	
3		7CAD-801150	Tensiometer	1	STRIAL#1192
///k//////////////////////////////////					
Instructions- calibrate and return					
				25	X 41A
Received	By_				

Date

W. O. 12-14-5

